

Michael O. Leavitt Dianne R. Nielson, Ph.D. Executive Director Don A. Ostler, P.E.

## 0015 State of Utah

## DEPARTMENT OF ENVIRONMENTAL QUALITY DIVISION OF WATER QUALITY

288 North 1460 West P.O. Box 144870 Salt Lake City, Utah 84114-4870 (801) 538-6146 (801) 538-6016 Fax (801) 536-4414 T.D.D. www.deq.state.ut.us Web

Water Quality Board

K.C. Shaw, P.E.

William R. Williams Vice Chairman

Robert G. Adams

Nan Bunker

Ray M. Child, C.P.A.

John R. Cushing, Mayor

Dianne R. Nielson, Ph.D.

Ronald C. Sims, Ph.D.

Douglas E. Thompson, Mayor

J. Ann Wechsler

Don A. Ostler, P.E. Executive Secretary

June 6, 2000

Mr. Rusty Netz, Environmental Coordinator Sunnyside Cogeneration Associates P.O. Box 10 East Carbon, UT 84520

Dear Rusty:

Subject:

Reconnaissance Inspection UT0024759

I conducted a Reconnaissance Inspection at Sunnyside Cogeneration Associates on May 10, 2000. Everything seemed to be in order and no violation of permit requirements were observed during the onsite inspection and no response to this report is needed.

If you have any questions please give me a call at (801) 538-6058.

Sincerely,

Michael D. Herkimer, Environmental Scientist

Michael D Verkimer

Permits & Compliance Section

MDH:cc

**Enclosure** 

cc:

Donna Inman, U.S. EPA Region VIII (W/encl)

Claron Bjork, Southeastern Utah District Health Dept. (W/encl)

Pam Grubaugh-Littig, DOGM (W/encl) David Ariotti, District Engineer (W/encl)

P:\WQ\PERMITS\MHERKIME\WP\NETZ.LTR

			United	States Environmenta Washington, D.		ency		Form Approved OMB No. 2040-0003 Approval Expires 7-31-85
		······································	Section	on A: National [	Data Systen	Coding		
1 [	Transaction Code N   2   5   3  UITI0	NPDES 010121475191		11 12 <u> 0</u>	Yr/Mo/Da  0 0 5 1 0  arks	Inspection Ty 17 18 <u>I R I</u>	19 <u>I</u>	<del></del>
21 <u>l</u>		1	1111	1111		1 1 1 1 1 1 1 1 1		66
	Reserved Facility Eva	luation Rating		ВІ		QA	Reserve	
67 <u>l</u>				71 <u>  D  </u>	72	<u> N </u> 73 <u>     </u> 74	75	1 1 1 1 1 80
				Section B: I	acility Data			
	and Location of Facility Inspected					Entry Time	i i	Permit Effective Date
P.O. B	IYSIDE COGENERATION ASSOCIAT BOX 10 CARBON, UTAH 84520			Exit Time/Date	F	v/1/97 Permit Expiration Date 1/31/02		
Name(s) of On-Site Representative(s)				Title(s)				Phone No(s)
RUSTY NETZ				ENVIRONMENTAL COORDINATOR				435) 888-4476
		·					L	
Name	, Address of Responsible Official			Title				
RAND	DY SCOTT			GENERAL MANAGER				
				Phone No.			(	Contacted
				(435) 888-4476				
		(S = S:	Section	C: Areas Evalu	ated Durin	g Inspection tory, N = Not Evaluated)		
	Permit		asurement			reatment		Operations & Maintenance
	Records/Reports	Laborato				pliance Schedules		Sludge Disposal
	Facility Site Review		Receiving V	Vater	Self	-Monitoring Program		Other:
		Section D: Sum	mary of Fir	ndings/Comme	nts (Attach	additional sheets if neces	sary)	
EVER	RYTHING LOOKS NORMAL. NO VIOI	LATIONS OF PE	RMIT REQ	UIREMENTS W	ERE NOTE	<b>).</b>		
							-	
Name	e(s) and Signature(s) of Inspector(s)		Agency/C	Dffice/Telephone			То	ate
	e(s) and Signature(s) of Inspector(s)		1 .	Office/Telephone			D	ate
		lemir	1 .				D	ate 6/6/00
MKE		kemir M	1 .	OF WATER Q				ate 6/6/00 ate 6/6/00
MIKE	HERKIMER Well Wales	lemir H	DIVISION Agency/C	OF WATER Q	UALITY			6/6/00
MIKE	HERKIMER Luchael Differs ature of Reviewer Leyle from	Emir M	DIVISION Agency/C	OF WATER Q	UALITY	Only		6/6/00
Signa	HERKIMER Luchael Differs ature of Reviewer Leyle from	kemer M	DIVISION Agency/C	OF WATER Q	UALITY	Only Date	D	6/6/00 ate //6/00 Compliance Status
Signa	HERKIMER  Le har Designature of Reviewer  LE J. SMITH	lemir H	DIVISION Agency/C	OF WATER Q	UALITY		D	6/6/00 ate 6/6/00